

FIG. 1






FIG. 2



20030710 56225001

FIG. 3




MIYAMOTO
STRUCTURE FOR PREVENTING FAILURE OF
CONNECTOR
Filed: January 23, 2002
Darryl Mexic
202-293-7060
2 of 8

Q68219


FIG. 4

2018210 "5622500"




2002T0 "Structure" 25001

Fig. 5




MIYAMOTO
STRUCTURE FOR PREVENTING FAILURE OF
CONNECTOR
Filed: January 23, 2002
Darryl Mexic
202-293-7060
4 of 8

Q68219




31. 10 0 15 20 35 50 100

FIG. 7



2022010 "36225001"

Fig. 8






Fig. 9